
WEIGHING INDICATOR user manual


# Model: TI-02

Please read this manual carefully before operation ----Important safety info ----Operating condition and other attentions ----Guarantee info

#### Important Safety And Operation Info




Please read the manual in details before operation.






Please use the right plug and right voltage Be much attention of 110V or 220V!!!




Don't clean the indicator with the flush water.




Don't touch the keypad with the items with sharp end.



Keep it away from the corruptive gas or liquid.



Don't open the indicator by yourself and please call the service people or our distributor when you get the problem with it.



Please recharge the scale on time to assure the health of the battery, and replace the battery if it runs out of life. The replaced battery must be handled correctly.

### INDEX

Specifications	4
Power	4
Before using	4
System power consumption	4
Display description	4
Basic function operation	5
Connection of load cell and RS232	5
Basic parameter setting	6
UF-1 A/D count	6
UF-2 High / Low limits setting	6
UF-3 Auto-power off	7
UF-4 Backlight setting	7
UF-5 Hold function (*)	7
UF-6 RS-232 output	8
UF-7 Speed setting (*)	10
UF-8 Zero tracking (*)	10
UF-9 G Value setting	11
UF-10 Filt setting	11
UF-12 Beep setting	11
Weight Calibrations (*)	12
ECF-1 Zero and Span Calibration	12
ECF-2 Zero Calibration	12
ECF-3 Span Calibration	12
Guarantee	13

### **SPECIFICATIONS**

Accuracy:Class IIINonlinear:≤0.01%F.SExcitation voltage:DC 5V,up to 4 load cells 350 ΩLarge display connector:Sampling serial output waySample rate:20 times per second (can select)

# POWER

Input: 120~240V Output: 9V/500mA Rechargeable battery: 6V/1.3AH

## BEFORE USING

- 1) Place this product on a firm and smooth place, don't place it in vibration or shaking, use bench for use on four only adjust foot, adjust the balance using the bubble level.
- 2) Use independent source, avoid other electrical disturbance.
- 3) Don't put any object on the platter when turn on the balance.
- 4) Please, turn on 2-3 minutes before using.
- 5) Avoid temperature change too large and air flow strenuous sites.
- 6) Don't overload the balance, don't exceed the maximal capacity.


### SYSTEM POWER CONSUMPTION

Main system power consumption: about 12mA

Main system power consumption (with backlight): about 36mA Main system power consumption (with backlight and RS-232): about 48mA Battery life: none backlight, about 320 hours.

# **DISPLAY DESCRIPTION**

TI-02 Model:



# **BASIC FUNCTION OPERATION**

OFF
-----

Press and hold this key for 2 seconds to turn off the balance.

and this kow to turn on the holoned



Function 1. Press this key to turn on the balance
Function 2. To reset the weight to "0", but the display value has to be
lesser than $\pm$ 2% of maximum capacity.
Function 3. To subtract the container's weight.
Function 4. To move one space to the right or upward in setup mode.
Function 1. To select the desired weight unit.
Function 2. To exit from setup mode.



UNIT ESC

> **Function 1.** To view gross or net weight when the balance is on tare status. All other keys will be disabled when gross weight is activated. Function 2. To increase values upward in setup mode.



Function 1. Key of confirmation in setup mode.

- Function 2. Manually transmitting data through RS232 to computer or printer.
- Function 3. To accumulate weights, the max of the weight times is 9999




Function 1. To recall accumulations


Function 2. Long press the key will clear accumulated weight **Function 3.** To move one space to the left or downward in setup mode.

# **CONNECTION OF LOAD CELL AND RS232**

1) Connection of the load cell to indicator





INDICATOR		LOAD CELL
1		+Excitation
2		+Sense
3		-Excitation
4		-Sense
5		+Signal
6		(GND) shield
7		-Signal



INDICATOR	PC/PRINTER
1	RXD
2	TXD
3	GND
4	NC


### **BASIC PARAMETER SETTING**





Hold 1 : Animal (motion) Hold function

Hold 2 : Peak value hold (when held can press any key to cancel)



232	9	: Manual accumulate output – Format 4	
232 1	0	: Auto accumulate output – Format 4	
232 1	1	~ 232 13 : LP50 printer is used	

ST, GS, +

+

S/N

0001

0002

0002

1.0001b

WT/1b

2.205

2.205

4.410

1.0001b

Baud rate: B 1200	: Baud rate 1200
в 2400	: Baud rate 2400
в 4800	: Baud rate 4800
в 9600	: Baud rate 9600
В19200	: Baud rate 19200
B38400	: Baud rate 38400

Remarks:

Format 1 output examples :

Format 2 output examples :

Format 3 output examples :

Format 4 output examples :

TICKET NO.0001
G 3.0001b
T 1.0001b
N 2.0001b
TOTAL NUMBER
OF TICKETS 0001
TOTAL
NET 2.000

• Format 3 and format 4 if you want to print the total weight, press the twice, and the accumulative weight will be removed.

<sup>™+</sup> key

Communication Protocol:

UART signal of EIA-RS232 C Format:


- 1. Baud rate: 9600
- 2. Data bits : 8 bits
- 3. Parity bits: None
- 4. Stop bits : 1 bit

Format 1 (232 1 – 3):

HEAD1 (2 BYTES)	HEAD2 (2 BYTES)
OL – Overload	
ST – Stable	NT – Net weight

US – Unstable GS - Gross weight Fixed 18 BYTES ASCII (kggtlb) 1 2 1 1 2 1 1 2 3 4 5 6 7 8 1 2 HEAD1, HEAD2, DATA UNIT CR LF Fixed 21 BYTES ASCII (tl.T lboz) 23 4 5 6 78 9 2 B 2 2 1 1 1 1 1 1 4 1 2 CR LF HEAD1, HEAD2, DATA UNIT Fixed 19 BYTES ASCII (pcs) 1 2 1 2 1 1 2 3 5 6 7 8 2 3 1 2 1 4 1 HEAD1, HEAD2, DATA UNIT CR LF

#### **UF-7** Speed setting (\*)



- 1. Press the key to enter.
- 2. Press the  $_{Net/Gross}$  key to select the desired mode.
  - key to confirm.
- UF-8 Zero tracking(\*)

3. Press the

- Modes:Zp0: OFFZp1: One division tracking at zeroZp2: Two division tracking at zeroZp3: Three division tracking at zeroZp4: Four division tracking at zeroZp5: Five division tracking at zero
- 1. Press the key to enter.
- 2. Press the Net/Gross key to select the desired mode.
- 3. Press the key to confirm.

### **UF-9 G** Value setting

- 1. Press the key to display the G value of manufacture place.
- 2. If set the G value of local press the key and then press the Zero/Tare or




3. Press the

key and Net/Gross key to input the new G value.

UF-10 Filt setting

M+




Press the key to enter.
Press the key to select the desired mode.


key to confirm.

3. Press the key to confirm.


# UF-12 Beep setting




# Weight Calibrations (\*)









3. The scale will return back to weighing mode automatically.

#### ECF-3 Span Calibration

- 1. Press the key to enter, display will show the calibration weight 00.6.000.
- 2. Use the keys and and to select the digit, press Net/Gross key to input the

weight value.

3. Put the calibration weight on the platter and press the M+

key to calibrate.

The scale will return back to weighing mode automatically.

# **GUARANTEE**

This scale is guaranteed for one year from the delivery date. The guarantee covers any fabrication defect of the material.

During this period Gravity covers the labour cost and the spare parts necessary for the reparation of the scale.

This guarantee does not cover the failures caused by an inappropriate use or overcharge.

The guarantee does not cover the freight cost (transport) necessary to repair the scale.

Officially Distributed By

